



SPIRIT FITNESS

A Heritage of Quality | The Spirit of Innovation

Инструкция по сборке машины Смита



Руководство пользователя



A Heritage of Quality | The Spirit of Innovation
SPIRIT FITNESS





A Heritage of Quality | The Spirit of Innovation
SPIRIT FITNESS



A Heritage of Quality | The Spirit of Innovation
SPIRIT FITNESS


1




1  X4
M12X30


2  X8
M12

3  X16 4  X8
M12 M12


4  X8
M12

5  X4
M12X105


2





3




10





10  X12
M8X10

20  X2
 $\Phi 28 * \Phi 18.5 * 30$




20






1  X4
M12X30



2  X8
M12



3  X16
M10


4  X8
M12


5  X4
M10X80

6  X2
M10X25 

7  X4
M10 

8  X2
M10 

9  X16
M8X10

10  X6
 $\Phi 62 \times \Phi 31 \times 25$

10  X2
 $\Phi 28 * \Phi 18.5 * 30$